

FIS Basic Fiber Optic Tool Kit

- Canned Air (F1-1007S)
- PVC Electrical Tape (F1-0008)
- 4oz. Alcohol Bottle (F1-0007I)
- Fiber Stripper (F1-1300Y)
- FIS Connector Cleaner (F1-7020-C)
- Kevlar Scissors (F1-KS1)
- Jacket Stripper (F1-0016)
- Universal Continuity Tester (F1-5000U)
- Buffer Tube Stripper (F1-0017)
- Round Cable Slitter (MK02)
- 6" Side Cutting Pliers (THT-2140)
- (50) Foam Swabs (F1-0005)
- Matching Gel (F1-0001K)
- Kim Wipes (34-155)
- Utility Knife (F1-0023)
- Tweezers (F1-0019)
- Needle Nose Pliers (THT-1840)
- Piano Wire (F1-8265K)
- 4 Bit Screwdriver (F1-0027)
- Black Marker (F1-9104)
- Safety Glasses (WO1067G)
- (5) D-Gel Wipes (F1-1011)
- Black Work Mat (F1-0024)
- Fiber Disposal Unit (F1-8328C)
- Wire Marker Dispenser (KMM09)
- Ruler (RMC-6)
- Fabric Tape Measure (F1-8273)
- 1/2" Nut Driver (1UG30)
- (3) Economy Tie Labels (P50KIT)
- Rugged Carry Case (F10053EY)
- (5) Fusion Splice Sleeve (F1-1002C)
- 1Mtr 3mm Furcation (F00FR3RO)
- 1Mtr 900µm Furcation (F00FR900HW)



FIS Universal Epoxy Tool Kit (SC, FC, ST)

- Canned Air (F1-1007S)
- PVC Electrical Tape (F1-0008)
- 4oz. Alcohol Bottle (F1-0007I)
- Fiber Stripper (F1-1300Y)
- FIS Connector Cleaner (F1-7020-C)
- Kevlar Scissors (F1-KS1)
- Jacket Stripper (F1-0016)
- Universal Continuity Tester (F1-5000U)
- Buffer Tube Stripper (F1-0017)
- Round Cable Slitter (MK02)
- 6" Side Cutting Pliers (THT-2140)
- (50) Foam Swabs (F1-0005)
- Matching Gel (F1-0001K)
- Kim Wipes (34-155)
- Utility Knife (F1-0023)
- Tweezers (F1-0019)
- Needle Nose Pliers (THT-1840)
- Piano Wire (F1-8265K)
- 4 Bit Screwdriver (F1-0027)
- Black Marker (F1-9104)
- Safety Glasses (WO1067G)
- (5) D-Gel Wipes (F1-1011)
- Black Work Mat (F1-0024)
- Fiber Disposal Unit (F1-8328C)
- Wire Marker Dispenser (KMM09)
- Ruler (RMC-6)
- Fabric Tape Measure (F1-8273)
- 1/2" Nut Driver (1UG30)
- (3) Economy Tie Labels (P50KIT)
- Rugged Carry Case (F10053EY)
- (5) Fusion Splice Sleeve (F1-1002C)
- 1Mtr 3mm Furcation (F00FR3RO)
- 1Mtr 900µm Furcation (F00FR900HW) FIS Basic Tool Kit (F1-0053)
- Carbide Scribe (F1-9773)
- Universal Crimp Tool (F1-3227)
- Rubber Polish Pad (PP-575)
- Universal Microscope (F1-9786)
- Glass Polish Plate (F1-9111)
- (5) Syringes (5014733IR5)
- (5) 0.3µm Polish Film Sheet (F1-0102-03S)
- (5) 1µm Polish Film Sheet (F1-0102-1S)
- (5) 5µm Polish Film Sheet (F1-0102-5S)
- Universal Polish Puck (F1-6925UN)
- Instructions for FIS Connectors ST, FC & SC
- (5) FIS 4gr. Blue Dye Epoxy (T60-065-B4)



FIS FUSION SPLICING TOOL KIT

- Canned Air (F1-1007S)
- PVC Electrical Tape (F1-0008)
- 4oz. Alcohol Bottle (F1-0007I)
- Fiber Stripper (F1-1300Y)
- FIS Connector Cleaner (F1-7020-C)
- Kevlar Scissors (F1-KS1)
- Jacket Stripper (F1-0016)
- Universal Continuity Tester (F1-5000U)
- Buffer Tube Stripper (F1-0017)
- Round Cable Slitter (MK02)
- 6" Side Cutting Pliers (THT-2140)
- (50) Foam Swabs (F1-0005)
- Matching Gel (F1-0001K)
- Kim Wipes (34-155)
- Utility Knife (F1-0023)
- Tweezers (F1-0019)
- Needle Nose Pliers (THT-1840)
- Piano Wire (F1-8265K)
- 4 Bit Screwdriver (F1-0027)
- Black Marker (F1-9104)
- Safety Glasses (WO1067G)
- (5) D-Gel Wipes (F1-1011)
- Black Work Mat (F1-0024)
- Fiber Disposal Unit (F1-8328C)
- Wire Marker Dispenser (KMM09)
- Ruler (RMC-6)
- Fabric Tape Measure (F1-8273)
- 1/2" Nut Driver (1UG30)
- (3) Economy Tie Labels (P50KIT)
- Rugged Carry Case (F10053EY)
- (5) Fusion Splice Sleeve (F1-1002C)
- 1Mtr 3mm Furcation (F00FR3RO)
- 1Mtr 900µm Furcation (F00FR900HW)
- Cable Cutters (F1-1817)
- Miller Jacket Slitter (F1-114)
- Flashlight (F1-605)
- Spatula (10033301)
- (12) D'Gel Pre-Moistened Wipes (F1-1011)
- 50 Pack Protection Sleeves 60mm (F1-S25C)
- Optional CT30A Cleaver (S014080)



.....

FIS FIBER OPTIC CLEANING KIT

- Compressed Air (10oz) (F1-1007S)
- 2.5mm Foam Swabs (5pk) (F1-25184)
- 1.25mm Wrapped Swabs (5pk) (F1-25123)
- Kim Wipes (34-155)
- Optic Prep Tissue (50pk) (F1-1003)
- FIS Connector Cleaner (F1-7020-C)
- 4 oz. Bottle of Alcohol (F1-0007SP)

